

User interface, command processor, human engineering

- 1) Should be able to set time restrictions on any subprocess called from the C.P. & be able to add more time when it runs out (or about, of course). Including editor, assembler, ...
- 2) Should be able to change his weight:
down at any time
up, so long as it doesn't oversubscribe the system
- 3) Should have access (optional) to timing of subsystems called
- 4) Should have 2 flavors of interrupt fornic
"mild" - directed to some user subprocess
"major" - directed to some system subprocess